

The 2 key buttons are to adjust RS485 functions

Setup Cancel OFF ON Flash Strobe Fade Smooth

R G B W

MCL Remote Controller

ON/OFF Switch

Colour(s) Calibration

By Rainbow Flash mode, in every 1 sec, it di splays 1 color. This display can go up to 16 colors.

 By Rainbow Strobe mode, in every 5 sec, it displays 1 color. This display can go up to 16 colors.

 Gradual change(fade): fade change mode, can go up to 16 colors

Gradual change(smooth): smooth change mode, can go up to 16 colors.

The 4 Key buttons are to adjust the brightness.

Input Voltage: 3V dc

Frequency: 38KHZ

Angle: 30

01741

